



PORTER-CABLE SPEEDMATIC® ROUTER

WARNING: Electrical repairs should only be attempted by trained repairmen. Contact the nearest Porter-Cable Service Center or other competent repair center

75361
75362
75371
75372



120V OR 220V
WIRING DIAGRAM

Parts List for 75372 Type 1

Item Number	Part Number	Description	Qty Required
1	881083	ARMATURE (220)	1
1	874474	ARMATURE	1
1	875931	FAN	1
2	000000-00	No Longer Available	1
2	874475	FIELD	1
3	N031634	BRUSH	2
3	698844	BRUSH HOLDER	2
4	873227	ROCKER SWITCH	1
4	873222	PLATE	1
5	875691	CORDSET	1
5	879884	CORD	1
5	698855	CORD	1
6	698874	BRUSH INSULATOR	2
7	698872	SPRING	10
8	882703	SCREW	10
10	852310	SCREW	10
11	330003-75	BEARING, BALL	3
11	146555-01	BEARING, BALL	3
15	698811	BRG RETAINER	3
52	877297	MOTOR HOUSING	1
52	A23246	LOWER HOUSING ASSY	1
52	A22442	TOP CAP	1
81	859069	PLUG	1
83	698807	CHUCK	1
83	42950	1/2 INCH COLLET ASSY	1
83	5140103-66	COLLET ASSY.	1
83	876671	COLLET 1/2 INCH	1

COPYRIGHT© 2005. All Rights Reserved.

Parts list, pricing, and availability subject to change. Please visit www.dewaltservicenet.com for current parts information.

Parts List for 75372 Type 1

Item Number	Part Number	Description	Qty Required
83	875893	COLLET NUT	1
83	823030	SNAP-RING	1
88	892778	SCREW	10
94	899411	SCREW	10
122	872520	SCREW	10
210	800980	PIN	4
217	849819	SCREW	10
219	874845	BUSHING KIT	1
219	874514	SCREW	10
220	872766	SPRING-STRAIN RELVR	1
221	A22709	OPEN-END WRENCH	1
221	A22709	OPEN-END WRENCH	1
222	689032	CONNECTOR	1

COPYRIGHT© 2005. All Rights Reserved.

Parts list, pricing, and availability subject to change. Please visit www.dewaltservicenet.com for current parts information.