





# HITACHI

## SCREW DRIVER

### Model W 6V

ITEM NO.	PART NO.	NO. USED	DESCRIPTION	SUPPLY Q'TY	ITEM NO.	PART NO.	NO. USED	DESCRIPTION	SUPPLY Q'TY
1	971511Z	1	No.2 Plus Bit (A)		23	949228	2	Machine Screw M4×40	10
2	982555Z	1	Locator		24	982556P	1	Stator	
3	950514	2	Tapping Screw D4×40		25	931701	1	Bearing Lock	
4	949453	6	Spring Washer	10	26	626VVM	1	Ball Bearing 626VVMC2ERPS2S	
5	950515	2	Tapping Screw D4×50		27	982591	1	Housing	
6	982561	1	Gear Cover		28	—	1	Name Plate	
7	982564	1	O-Ring 1AP-15		30	982095	3	Tapping Screw D4×20	
8	971468	1	Fringer (A)		31	950527	1	Handle Cover	
9	982554Z	1	Magnetic Bit Holder		32	950565	1	HITACHI Label	
10	872573	1	Set Ring		33	999041	1	Carbon Brush	2
11	959148	2	Ball D3.17	10		999080Z	1	Carbon Brush (Auto Stop Type)	2
12	982572	1	Socket		34	955203	2	Brush Holder	
13	943523	1	Spring (A)		35	949554	2	Nut M4	10
14	959154	1	Steel Ball D5.55	10	36	971510	1	Packing (A)	
15	982552	1	Gear Shaft		37	985347	1	Speed Control Switch	
16	982571	1	Gear		38	982566Z	1	Reversing Switch	
17	950511	1	Hook		40	930487	1	Cord Armor D8.2	
18	608VVM	1	Ball Bearing 608VVMC2EPS2L		41	982565	1	Support (B)	
19	982550Z	1	Inner Cover		42	937631	1	Cord Clip	
20	609VVM	1	Ball Bearing 609VVMC2PS2S		43	954004	2	Tapping Screw D4×16	
21	982557C	1	Armature		44	500240Z	1	Cord	
22	950504	1	Fan Guide		49	981373	2	Tube (D) for cord	